Capital Fund Program - Five-Year Action Plan

Status: Draft Approval Date: Approved By: 02/28/2022

Part	I: Summary					
	Name: Housing and Community Development Tucson	1	Locality (City/County & State) X Original 5-Year Plan		Revised 5-Year Plan (Revision No:	
A.	Development Number and Name	Work Statement for Year 1 2022	Work Statement for Year 2 2023	Work Statement for Year 3 2024	Work Statement for Year 4 2025	Work Statement for Year 5 2026
	SCATTERED SITES (AZ004300110)	\$236,500.00	\$210,000.00	\$265,000.00	\$255,000.00	\$220,000.00
	SCATTERED SITES (AZ004400111)	\$260,000.00	\$258,000.00	\$220,000.00	\$260,000.00	\$220,000.00
	SCATTERED SITES (AZ004600113)	\$377,000.00	\$230,000.00	\$258,000.00	\$152,000.00	\$230,000.00
	SCATTERED SITES (AZ004500112)	\$366,000.00	\$400,000.00	\$320,000.00	\$512,000.00	\$310,000.00
	POSADAS SENTINEL, PH. I (AZ004000051)	\$276,500.00	\$317,000.00	\$313,000.00	\$313,000.00	\$369,000.00
	AUTHORITY-WIDE	\$918,086.00	\$916,086.00	\$919,086.00	\$927,086.00	\$905,086.00
	MIXED FINANCE DEVELOPMENT TUCSON HOUSE	\$67,000.00	\$35,000.00	\$121,000.00	\$57,000.00	\$57,000.00
	LANDER APTS - PHASE II (AZ004100115)	\$45,000.00	\$180,000.00	\$130,000.00	\$70,000.00	\$235,000.00

Work Statement for Year 1

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	SCATTERED SITES (AZ004300110)			\$236,500.00
ID0040	Electrical Hazard (Housing Related Hazards (1480)-Hazard Controls-Other, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Site Work (1480)-Electric Distribution)	Make the necessary repairs to Federal Pacific Stab-Lok panels identified in the PNA report know to be potential hazards due to design in the following unit: 1550 S Marmora Ave (106)		\$1,500.00
ID0051	AMP-3 Roof Replacement(Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs)	Replace deteriorated shingle or BUR roof systems at the following locations with new: Unit 27 - 1774 W Calle Acapulco Unit 28 - 1786 W Calle Acapulco Unit 29 - 1794 W Calle Acapulco Unit 57 - 414 E Alturas St Unit 90 - 1555 W. Calle Guadalajara		\$120,000.00
ID0299	AMP-3 Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior (1480)-Exterior (1480)-Exterior (1480)-Exterior (1480)-Building Unit-Exterior (1480)-Building Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Appliang Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Flectric Distribution,Dwelling Unit-Site Work (1480)-Encing,Dwelling Unit-Site Work (1480)-Encing,Dw	Perform the necessary non-routine modifications to the following identified units: Unit 26 - 2518 N Estrella Ave Unit 90 - 1555 W. Calle Guadalajara Unit 111 - 2675 N. Leah Pl Unit 89 - 1440 N. 2nd Ave Unit 95 - 2008 W. Rufus Cir		\$100,000.00

Work Statement for Year 1

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0315	AMP-3 Site Improvements (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Seal Coat, Dwelling Unit-Site Work (1480)-Signage, Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1010-1030 N. 6th. Ave.		\$15,000.00
	SCATTERED SITES (AZ004400111)			\$260,000.00
ID0057	AMP-4 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated roof systems at the following locations: Unit 127 - 2109 E Dakota St. \$40K Unit 100 - 1512 E. Ohio St. \$36K Unit 147 - 1507 E. El Atajo St. \$17K Unit 17 - 408 W Oklahoma St \$20K Unit 18 - 410 W Oklahoma St \$20K		\$140,000.00
ID0226	AMP-4 Site Improvements (Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Fence Painting, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Other, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Seal Coat, Dwelling Unit-Site Work (1480)-Storm Drainage, Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1- 6868 S 4TH AV \$3200 2- 1339 E OHIO ST \$4500 3- Provide A&E Design for Electrical Improvements at these locations: N. 4th. Ave., Southland, and Delano \$4300		\$20,000.00
ID0260	AMP-4 Unit Modernization (Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Counters and Sinks,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior	Perform the necessary non-routine modifications to the following units: 1- 827 W. Montana St (94) 2- 650 W Calle Garcia (114) 3- 4133 E. Canada Strav (52) 4- 316 W Lerdo Rd (51)		\$100,000.00

Electrical Hazard (Housing Related Hazards (1480)-Hazard Controls-Other, Dwelling Unit-Interior

(1480)-Electrical, Dwelling Unit-Site Work (1480)-Electric Distribution)

ID0432

Part II: Sup	oporting Pages - Physical Needs Work Statements (s)			
Work State	ment for Year 1 2022			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers)			ļ
	SCATTERED SITES (AZ004600113)			\$377,000.00
ID0136	AMP-6 Roof Replacement(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated shingle or BUR roof systems with new. 1- (53) 3471 S Fairbanks Ave. 2- (72) 3501 E Prudence St. 3- (119) 3720 E Serena Lane 4- (1) 1511 N Sonoita Avenue		\$125,000.00
ID0302	AMP-6 Unit Modernization (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Interior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and	Perform the necessary non-routine modifications to the following identified units: 1- (111) 3931 S Lone Palm Dr 2- (74) 4741 S Prudence Rd 3- (98) 4663 S Rosette Ave 4- (19) 7227 E Luana Pl 5- (129) 5636 E Camden St		\$100,000.00
ID0431	AMP-6 CT - Roof Replacement(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated BUR roof systems with new. CT Towers 1635 N. Craycroft Rd.		\$140,000.00

Make the necessary repairs to Federal Pacific Stab-Lok panels identified in the

PNA report know to be potential hazards due to design in the following units:

2922 S Portia Ave (110)
 3720 S Serena Ln (119)
 4742 S Goldenrod Dr (94)

\$12,000.00

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work State	ment for Year 1 2022				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost	
		(4) 4741 S Prudence Rd (74) (5) 7655 E Pecan St (81) (6) 6725 E Brooks Dr (55) (7) 7426 E 18th St (31) (8) 6425 E Eli Dr (6)			
	SCATTERED SITES (AZ004500112)			\$366,000.00	
ID0148	AMP-5 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated shingle or BUR roof systems with new at the following locations: (174-177) - 3327 E Glenn St. \$50K (74) - 1009-11 E Waverly St. \$25K (6) - 701 S Rosemont Ave \$25K		\$120,000.00	
ID0152	AMP-5 Site Improvements(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	1- Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 751-781 E. Navajo Rd. \$120K 2- A&E plan & design options: parking, laundry, etc. \$10K 3- A&E exterior lighting & service entrance upgrades. \$10K		\$140,000.00	
ID0301	AMP-5 Unit Modernization (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior	Perform the necessary non-routine modifications to the following identified units: (114-123) 380 E Pastime Rd. (A-T) As they become vacant. (28) - 224 W Knox Dr (36) - 1007 E Knox Dr (168-69) - 2831-33 N. Edith - Casualty Loss/Modernization		\$100,000.00	

Part II: Suj	oporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1 2022					
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost	
	Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Fence Painting, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Sewer Lines - Mains, Dwelling Unit-Site Work (1480)-Water Lines/Mains)			I	
ID0424	Electrical Hazard (Housing Related Hazards (1480)-Hazard Controls-Other, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Site Work (1480)-Electric Distribution)	Make the necessary repairs to Federal Pacific Stab-Lok panels identified in the PNA report know to be potential hazards due to design in the following units: (1) (29) 1709 S Winstel Ave (2) (25) 1650 S Beverly Ave (3) (147) 5372 E 32nd St (4) (127) 2434 E Helen St		\$6,000.00	
	POSADAS SENTINEL, PH. I (AZ004000051)			\$276,500.00	
ID0159	Posadas 140- Water Heaters(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters)	Deteriorated water heaters have reached the end of their life expectancy and need to be replaced with new high efficiency models. Units 6-10 of 60		\$12,500.00	
ID0399	Posadas 140- Roof Replacement(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Roofs)	Replace identified existing deteriorated roof systems at the following locations: 1- PHA - (2-3) 406 W Calle Posadas #1&2 2- Scattered Sites= Unit 35 - 571 W Placita Durango Unit 8 - 7035 E Typhoon Flyer Way Unit 7- 7018 E Mitchell Flyer Rd Unit 10 - 2333 W Silverbell Tree Dr		\$142,000.00	

Work Statement for Year 1

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0405	Posadas 140- Replace HVAC System (Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System)	Replace deteriorated HVAC systems at the following locations: PHA - (2-3) 406 W Calle Posadas #1&2		\$16,000.00
ID0409	Posadas 140- Site Work(Dwelling Unit-Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Landscape)	A&E for Phase two of landscaping, curb appeal project.		\$6,000.00
ID0433	Posadas - Unit Modernization (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and AUTHORITY-WIDE (NAWASD)	Perform the necessary non-routine modifications to the following units: Unit 35 - 571 W Placita Durango Unit 8 - 7035 E Typhoon Flyer Way Unit 7- 7018 E Mitchell Flyer Rd Unit 10 - 2333 W Silverbell Tree Dr		\$100,000.00 \$918,086.00
ID0187	2022 - Management Improvements(Management Improvement (1408)-Empowerment Activities,Management Improvement (1408)-Equal Opportunity,Management Improvement (1408)-Other)	PHA Homeowner Activities. Training for PHA staff in operations, procurement and procedures.		\$52,418.00
ID0189	2022 - Operations(Operations (1406))	24% of the total grant amount distributed to AMPS		\$611,060.00

Work Statement for Year 1

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0190	2022 - Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	Administrative costs necessary for the planning, design, implementation and monitoring of physical and Management Improvements.		\$254,608.00
	MIXED FINANCE DEVELOPMENT TUCSON HOUSE (AZ004000048)			\$67,000.00
ID0274	Bathroom Modifications(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Tub, showers, surrounds, sinks and vanities are in need of specific non-routine repairs in units: 219,320,413,504,614,702,819, 923		\$12,000.00
ID0276	Physical Plant Repairs(Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Central Boiler,Non-Dwelling Construction - Mechanical (1480)-Central Chiller,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Electric Distribution,Non-Dwelling Construction - Mechanical (1480)-Generator,Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters,Non-Dwelling Construction - Mechanical (1480)-Water Distribution)	Make the necessary repairs "as needed" to HVAC, boilers, chillers, pumps, piping, generator, motors that provide heating, cooling and domestic hot water to the building residents. This is needed pending the anticipated award of the Choice Neighborhood Grant. Replace deteriorated HVAC chilled water pipes as reported by tenants. Units not know until they begin to leak.		\$20,000.00
ID0277	Building Repairs(Contract Administration (1480)-Other Fees and Costs,Non-Dwelling Construction-New Construction (1480)-Other,Non-Dwelling Construction-New Construction (1480)-Shop,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Shop)	Contract with A&E services to evaluate, design, draw plans and provide estimated cost to repair deteriorated concrete ceiling in the physical plant room.		\$10,000.00
ID0282	Contract Administration - Relocation Costs(Contract Administration (1480)-Relocation)	Anticipated resident relocation costs pending the award of the Choice Neighborhood Grant.		\$5,000.00

Work Statement for Year 1

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0285	Site Improvements(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Striping,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Site Work (1480)-Lighting)	Replace deteriorated light fixtures at covered walkways and parking areas. Install bollards at main water line near loading dock.		\$10,000.00
ID0388	Elevator Modernization(Non-Dwelling Construction - Mechanical (1480)-Smoke/Fire Detection,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Electric Distribution,Non-Dwelling Construction - Mechanical (1480)-Elevator,Non-Dwelling Construction - Mechanical (1480)-Fire Suppression System,Non-Dwelling Construction - Mechanical (1480)-Generator,Non-Dwelling Construction - Mechanical (1480)-Security - Fire Alarm)	The (3) elevators have reached the end of their life expectancy, abnormal breakdowns, parts are not available, one elevator is out of service due to fire damage posing an immediate threat to the health and safety of the residents. Adding a contingency in the event that actual project expenses exceed the estimated cost.		\$10,000.00
	LANDER APTS - PHASE II (AZ004100115)			\$45,000.00
ID0374	LG- Site Improvement - A&E(Contract Administration (1480)-Other Fees and Costs)	Procure an A&E firm to design plans for the replacement of deteriorated exterior lighting with new energy efficient lighting and oversee the installation process at the Lander Gardens Complex (115).		\$15,000.00
ID0417	Lander Gardens - Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Perform the necessary non-routine modifications to vacated units as they become available. Due to a low vacancy rate as a unit becomes available it will be put on off line status undergo Modernization.		\$30,000.00
	Subtotal of Estimated Cost			\$2,546,086.00

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	SCATTERED SITES (AZ004300110)			\$210,000.00
ID0166	AMP-3 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace the existing deteriorated roof systems at following locations: 1-3031 N. Castro \$65K Unit (47-52) 2-870 & 871 W. Calle Sur \$58K (78-83)		\$100,000.00
ID0169	AMP-3 Site Improvements -Parking(Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 211 N. Delano St.		\$10,000.00
ID0303	AMP-3 Unit Modernization (Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports - Surface Garage,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Cutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Perform the necessary non-routine modifications to the following identified units: 1-2210 W Window Rock Dr (98) 2-105 E Lee St (85) 3-1755 S. San Antonio (119) 4-1717 S Via Hondo (55)		\$100,000.00 \$258,000.00

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0172	AMP-4 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace the existing deteriorated roof systems at following locations: 1-1810 E. Oregon St. (50) 2-2161 E. Honeysuckle St. (77) 3-4751 S. Warren Ave. (106) 4-4701 S Warren Ave. (109)		\$100,000.00
ID0192	AMP-4 Aluminum Fascia (Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Other)	Deteriorated wood and paint on fascia and posts are creating a REAC inspection and maintenance paint failure issue. Covering fascia and posts with aluminum will resolve these issues. This will be done at the following locations: 1-2141 E. Balsam Circle 2-302 W. Virginia St. 3-710 W. Calle Romeo		\$8,000.00
ID0225	AMP-4 Site Improvements (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Other, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Seal Coat, Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 316,340,348,356 W Lerdo Rd.		\$12,000.00
ID0304	AMP-4 Unit Modernization (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc, Dwelling Unit-Exterior (1480)-Building Slab, Dwelling Unit-Exterior (1480)-Carports -Surface Garage, Dwelling Unit-Exterior (1480)-Exterior Doors, Dwelling Unit-Exterior (1480)-Exterior Lighting, Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Gutters - Downspouts, Dwelling Unit-Exterior (1480)-Landings and Railings, Dwelling Unit-Exterior (1480)-Mail Facilities, Dwelling Unit-Exterior (1480)-Apofiances, Dwelling Unit-Exterior (1480)-Windows, Dwelling Unit-Interior (1480)-Appliances, Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Interior Painting (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Site Work (1480)-Tubs and Showers, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Bunit-Site Work (1480)-Fence Painting, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Landscape, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Seal Coat, Dwelling Unit-Site Work (1480)-Sewer Lines - Mains, Dwelling Unit-Si	Perform the necessary non-routine modifications to the following identified units: 1- 340 W. Lerdo Rd (42) 2- 1512 E. Ohio St (100) 3- 2161 E. Honeysuckle St (77) 4- 316 W. Wedwick St (117)		\$138,000.00

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	SCATTERED SITES (AZ004500112)			\$400,000.00
ID0175	AMP-5 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated shingle or BUR roof systems with new at the following locations: 1052-1120 E. Irwin Place		\$100,000.00
ID0179	AMP-5 Site Improvements - Parking(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1-4017-4049 E. Fairmount St. 2-3605 E Bellevue St Apt #1& #2 3-2440-2462 N. Edith Blvd.		\$50,000.00
ID0305	AMP-5 Unit Modernization (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Gitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Welchanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fence,Dwelling Unit-Site Work (1480)-Fence,Dwelling Unit-Site Work (1480)-Fence,Dwelling Unit-Site Work (1480)-Fence,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fenc	Perform the necessary non-routine modifications to the following identified units: (218) - 2021 S Cloverland Blvd (7)- 2233 E 17TH ST (29) - 3052 N Dodge Blvd (10) - 1318 S Rosemont Ave (114-123) 380 E Pastime Rd. (A-T) As they become vacant.		\$100,000.00
ID0382	AMP-5 Site Improvements - Electrical (Dwelling Unit-Exterior (1480)-Exterior Lighting, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Lighting)	Make the necessary repairs to deteriorated electrical service panels per A&E design plans at the 380 E. Pastime Rd. Complex.		\$150,000.00

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	SCATTERED SITES (AZ004600113)			\$230,000.00
ID0182	AMP-6 Roof Replacement(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated shingle or BUR roof systems with new. 1- 3931 E Lone Palm Dr. 2- 6635 E Fayette St 3- 6717 E Calle Dened 4- 7451 E Stella Rd.		\$100,000.00
ID0184	AMP-6 Aluminum Fascia (Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Other, Dwelling Unit-Exterior (1480)-Roofs)	Deteriorated wood and paint on fascia and posts are creating a REAC inspection and maintenance paint failure issue. Covering fascia and posts with aluminum will resolve these issues. This will be done at the following locations: 1-2638 S Desert Cavern Place (159) 270 LF 2-2668 S Desert Cavern Place (144) 270 LF 3-8302 E Stella Rd. (149) 230 LF 4-6450 E. Calle Capella (14) 200 LF 5-8011 E Sundew Dr. (142) 300 LF 6-5840 E Elida St. (121) 240 LF 7-9581 E 33rd. St. (83) 230 LF 8-6422 S Wheaton Dr. (161) 200 LF		\$30,000.00
ID0306	AMP-6 Unit Modernization (Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gunit-Exterior (1480)-Builing Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Balconies-Porches-Railings-etc)	Perform the necessary non-routine modifications to the following identified units: 1- 3217 S Winona Cir (96) 2- 3440 S Marcia Pl (125) 3- 4742 S Goldenrod Dr (94) 4- 9871 E Marianne St (84)		\$100,000.00

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	AUTHORITY-WIDE (NAWASD)			\$916,086.00
ID0199	2023 - Management Improvements(Management Improvement (1408)-Empowerment Activities,Management Improvement (1408)-Equal Opportunity,Management Improvement (1408)- Other)	PHA Homeowner Activities. Training for PHA staff in operations, procurement and procedures.		\$50,418.00
ID0200	2023 - Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administrative costs necessary for the planning, design, implementation and monitoring of physical and Management Improvements.		\$254,608.00
ID0201	2023 - Operations(Operations (1406))	24% of the total grant amount distributed to AMPS		\$611,060.00
	POSADAS SENTINEL, PH. I (AZ004000051)			\$317,000.00
ID0252	Posadas 140 - Water Heaters(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters)	Deteriorated water heaters have reached the end of their life expectancy and need to be replaced with new high efficiency models. Units 11-20 of 60		\$25,000.00
ID0402	Posadas 140 - Roof Replacement(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Roofs)	Replace identified existing deteriorated roof systems at the following locations: Posadas PHA= (8-9) - 411 W Armijo St. 1&2 Scattered Sites = Unit 46 - 2591 E Knightsbridge Dr. Unit 32- 2404 W Silver Arrow Unit 9- 2956 N River Creek Pl Unit 13 - 2137 W Splitwood Pl		\$122,000.00

Part II: Sup	oporting Pages - Physical Needs Work Statements (s)			
Work State	ment for Year 2 2023			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0406	Posadas 140- Replace HVAC System (Dwelling Unit-Exterior (1480)-Other, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Plumbing, Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems, Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System)	Replace deteriorated HVAC systems at the following locations: PHA - (8-9) - 411 W Armijo St. #1 - #2		\$20,000.00
ID0410	Posadas 140- Site Work(Dwelling Unit-Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)- Landscape)	Phase II - Landscaping per A&E design.		\$50,000.00
ID0430	Posadas - Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Chter,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Bettic Distribution,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Encring,Dwelling Unit-Site Work (1480)-Enc	Perform the necessary non-routine modifications to the following identified units: Unit 46 - 2591 E Knightsbridge Dr. Unit 32 - 2404 W Silver Arrow Unit 9- 2956 N River Creek Pl Unit 13 - 2137 W Splitwood Pl		\$100,000.00
	MIXED FINANCE DEVELOPMENT TUCSON HOUSE (AZ004000048)			\$35,000.00

Work Statement for Year 2

	,			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0284	Bathroom Modifications(Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Tub, showers, surrounds, sinks and vanities are in need of specific non-routine repairs in units: 1026, 1124, 1204, 1314, 1420, 1521, 1519, and 1605.		\$10,000.00
ID0290	Contract Administration - Relocation Costs(Contract Administration (1480)-Relocation)	Anticipated resident relocation costs pending the award of the Choice Neighborhood Grant.		\$5,000.00
ID0390	Building Repairs(Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems, Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System, Non-Dwelling Construction - Mechanical (1480)-Other, Non-Dwelling Construction-New Construction (1480)-Other, Non-Dwelling Construction-New Construction (1480)-Shop, Non-Dwelling Interior (1480)-Mechanical, Non-Dwelling Interior (1480)-Other)	Non-routine repairs to malfunctioning air vent handler controls in hallways. Repairs to physical plant ceiling per A&E design plans.		\$20,000.00
	LANDER APTS - PHASE II (AZ004100115)			\$180,000.00
ID0375	LG- Site Improvement - Lighting(Dwelling Unit-Exterior (1480)-Exterior Lighting, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Lighting, Non-Dwelling Construction - Mechanical (1480)-Electric Distribution, Non-Dwelling Exterior (1480)-Lighting)	Install energy efficient security & safety lighting at Lander Gardens Complex per A&E electrical design.		\$150,000.00
ID0418	Lander Gardens - Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Perform the necessary non-routine modifications to vacated units as they become available. Due to a low vacancy rate as a unit becomes available it will be put on off line status undergo Modernization.		\$30,000.00

U.S. Department of Housing and Urban Development

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)					
Work Stater	nent for Year 2	2023				
Identifier	Development Number/Name		General Description of Major Work Categories	Quantity	Estimated Cost	
	Subtotal of Estimated Cost				\$2,546,086.00	

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	SCATTERED SITES (AZ004300110)			\$265,000.00
ID0206	AMP-3 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace the existing deteriorated roof systems at following locations: 1- 3437 N Flowing Wells Rd \$40K (53 & 54) 2- 1735 W King Ave \$19K (69) 3- 414-432 E Alturas St. \$40 (57,60-62) 4- 1400 S Gecko \$23K (88)		\$120,000.00
ID0212	AMP-3 Site improvements - Parking(Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 3031 N Castro Dr.		\$45,000.00
ID0307	AMP-3 Unit Modernization (Dwelling Unit-Interior (1480)-Interior Doors, Dwelling Unit-Interior (1480)-Interior Painting (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Eectric Distribution, Dwelling Unit-Site Work (1480)-Encing, Dwelling Unit-Site Work (1480)-Encing, Dwelling Unit-Site Work (1480)-Encing, Dwelling Unit-Site Work (1480)-Eactrong, Dwelling Unit-Site Work (1480)-Eactrong, Dwelling Unit-Site Work (1480)-Balconies-Porches-Railings-etc, Dwelling Unit-Exterior (1480)-Bulding, Dwelling Unit-Exterior (1480)-Exterior Doors, Dwelling Unit-Exterior (1480)-Exterior Lighting, Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Gutters - Downspouts, Dwelling Unit-Exterior (1480)-Landings and Railings, Dwelling Unit-Exterior (1480)-Mail Facilities, Dwelling Unit-Exterior (1480)-Roofs, Dwelling Unit-Exterior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Betrical Dwelling Unit-Interior (1480)-Betrical Dwelling Unit-Interior (1480)-Betrical Dwelling Unit-Int	Perform the necessary non-routine modifications to the following identified units: 1- 1400 S. Gecko Rd (88) 2- 215 E Water St (97) 3- 1821 S. San Antonio Dr (125)		\$100,000.00
	SCATTERED SITES (AZ004400111)			\$220,000.00

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0217	AMP-4 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace the existing deteriorated roof systems at following locations: 1- 5106 S. Freemont Dr. \$20K (102) 2- 5145 S. Freemont Dr. \$22K (54) 3- 5178 S. Via Laguna Blanca \$23 (165) 4- 6079 S. Place De La Seine \$22K (130) 5- 1422 S Tyndall Ave \$22K (28)		\$120,000.00
ID0308	AMP-4 Unit Modernization (Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Interior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Welling Unit-Interior (1480)-Welling Unit-Interior (1480)-Welling Unit-Interior (1480)-Welling Unit-Interior (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Enecting,Dwelling Unit-Site Work (1480)-Enecting,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Ewere Lines - Mains,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (Perform the necessary non-routine modifications to the following identified units: 1- 6036 S Fontana Ave (78) 2- 6636 Avenida Mirella Bonita (151) 3- 522 W Marcus Dr (120) 4- 302 W. Virginia St (111) 5- 812 E. Bantam Rd (47)		\$100,000.00
	SCATTERED SITES (AZ004500112)			\$320,000.00
ID0229	AMP-5 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated shingle or BUR roof systems with new at the following locations: 1- 1020 E Linden St. (132) 2- 840 N Bently Ave. (137) 3- 3351 E Bermuda St Apt #1-6 (209-14)		\$110,000.00

Work Statement for Year 3

	1					
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost		
ID0232	AMP-5 Aluminum Fascia (Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Other, Dwelling Unit-Exterior (1480)-Soffits)	Deteriorated wood and paint on fascia and posts are creating a REAC inspection and maintenance paint failure issue. Covering fascia and posts with aluminum will resolve these issues. This will be done at the following locations: 1- 4737 E 10th. St. (14) 2- 3052 E Dodge Blvd. (29) 3- 827 E Alturas (8) 4- 4724 E Lee St. (33) 5- 3487 N Sierra Springs (229) 6- 4274 E River Falls Dr. (230) 7- 4283 E Parting Waters Way (231) 8- 3201 E Flower St. (134)		\$20,000.00		
ID0235	AMP-5 Site Improvements(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1-2934-38 N. Palo Verde Blvd. 2-3506-28 E. 3rd. St.		\$70,000.00		
ID0309	AMP-5 Unit Modernization (Dwelling Unit-Exterior (1480)-Gutters - Downspouts, Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Landings and Railings, Dwelling Unit-Exterior (1480)-Mail Facilities, Dwelling Unit-Exterior (1480)-Roofs, Dwelling Unit-Exterior (1480)-Windows, Dwelling Unit-Interior (1480)-Appliances, Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Flooring, Dwelling Unit-Site Work (1480)-Flooring, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Fence Painting, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Balconies-Porches-Railings-etc, Dwelling Unit-Exterior (1480)-Building Slab, Dwelling Unit-Exterior (1480)-Exterior Lighting)	Perform the necessary non-routine modifications to the following identified units: 1- 2440 N Edith Blvd (77-87) 2- 2442 N Edith Blvd 3- 2444 N Edith Blvd 4- 2446 N Edith Blvd 5- 2462 N Edith Blvd 6- 380 E Pastime Rd. (A-T) (114-123)		\$120,000.00		

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	SCATTERED SITES (AZ004600113)			\$258,000.00
ID0242	AMP-6 Roof Replacement(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated shingle or BUR roof systems with new. 1- 9631 E 33rd St. 2- 1069 N Independence Ave. 3- 8120 E Lakeside Parkway 4- 8168 E Snakeroot Dr. 5- 9042 E Glenmount Dr. 6- 7426 E 18th St 7- 1570 N Maguire Ave		\$140,000.00
ID0245	AMP-6 Aluminum Fascia (Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Other, Dwelling Unit-Exterior (1480)-Roofs)	Deteriorated wood and paint on fascia and posts are creating a REAC inspection and maintenance paint failure issue. Covering fascia and posts with aluminum will resolve these issues. This will be done at the following locations: 1- 10333 E Roywood Way 2- 10373 E Roywood Way 3- 10380 E Danwood Way 4- 10452 E Haymarket St.		\$18,000.00
ID0310	AMP-6 Unit Modernization (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Flooring (non Hall)-Electrical,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Perform the necessary non-routine modifications to the following identified units: 1- 3002 S Prudence Rd 2- 4750 S Green Olive Dr. 3- 908 S Elmerita Ave 4- 6850 E 39th St		\$100,000.00

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	POSADAS SENTINEL, PH. I (AZ004000051)	<u>. 1</u>		\$313,000.00
ID0256	Posadas 140 - Water Heaters(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters)	Deteriorated water heaters have reached the end of their life expectancy and need to be replaced with new high efficiency models. Units 21-30 of 60		\$25,000.00
ID0403	Posadas 140 - Roof Replacement(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Roofs)	Replace identified existing deteriorated roof systems at the following locations: Posadas PHA: (21-22) - 451 W Armijo #1&2 Scattered: Unit 80 - 7036 S Placita Sorrento Unit 14- 2580 N Splitwood Pl Unit 15 - 2135 W Calle Campana de Plata Unit 4 - 2565 S Rook Ave		\$122,000.00
ID0407	Posadas 140- Replace HVAC System (Dwelling Unit-Exterior (1480)-Other, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Plumbing, Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems, Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System)	Replace deteriorated HVAC systems at the following locations: PHA - (21-22) - 451 W Armijo #1 - #2		\$16,000.00
ID0411	Posadas 140- Site Work(Dwelling Unit-Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Landscape)	Phase II - Landscaping per A&E design.		\$50,000.00
ID0434	Posadas - Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non Counters and Sinks,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non Counters and Sinks,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non Counters and Sinks,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non Counters Co	Perform the necessary non-routine modifications to the following identified units: Unit 80 - 7036 S Placita Sorrento Unit 14- 2580 N Splitwood Pl Unit 15 - 2135 W Calle Campana de Plata Unit 11 - 4112 N 1st Ave		\$100,000.00

Work State	ment for Year 3 2024			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-			1
	MIXED FINANCE DEVELOPMENT TUCSON HOUSE (AZ004000048)			\$121,000.00
ID0286	Physical Plant Repairs(Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Central Boiler,Non-Dwelling Construction - Mechanical (1480)-Central Chiller,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Electric Distribution,Non-Dwelling Construction - Mechanical (1480)-Fire Suppression System,Non-Dwelling Construction - Mechanical (1480)-Generator,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters,Non-Dwelling Construction - Mechanical (1480)-Other,Non-Dwelling Construction - Mechanical (1480)-Water Distribution)	Make the necessary repairs "as needed" to HVAC, boilers, chillers, pumps, piping, generator, motors that provide heating, cooling and domestic hot water to the building residents. This is needed pending the anticipated award of the Choice Neighborhood Grant. Replace sump pump motor and controls. \$12K Replace defective boiler tubes. \$10K Replace leaking chiller & heating piping. \$10K		\$32,000.00
ID0287	Site Improvements(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Striping,Non-Dwelling Site Work (1480)-Fencing)	Make necessary repairs "as needed" to parking lot asphalt pending the award of the Choice Neighborhood Grant. Repair fencing at west side of property to include dog run, fencing to loading dock and garden area.		\$20,000.00
ID0289	Bathroom Modifications(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Tub, showers, surrounds, sinks and vanities are in need of specific non-routine repairs in units: 224, 226, 420, 522, 625, 712, 815, 902		\$12,000.00

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cos
ID0293	Building Repairs(Non-Dwelling Construction - Mechanical (1480)-Other,Non-Dwelling Construction - Mechanical (1480)-Trash Compactor,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other)	Non-routine repairs to trash chute doors and add an enzyme injection system to alleviate odors.		\$52,000.00
ID0391	Contract Administration - Relocation Costs(Contract Administration (1480)-Relocation)	Anticipated resident relocation costs pending the award of the Choice Neighborhood Grant.		\$5,000.00
	AUTHORITY-WIDE (NAWASD)			\$919,086.00
ID0296	2024 - Operations(Operations (1406))	24% of the total grant amount distributed to AMPS		\$611,060.00
ID0297	2024 - Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	Administrative costs necessary for the planning, design, implementation and monitoring of physical and Management Improvements.		\$254,608.00
ID0298	2024 - Management Improvements(Management Improvement (1408)-Other, Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity)	PHA Homeowner Activities. Training for PHA staff in operations, procurement and procedures.		\$53,418.00
	LANDER APTS - PHASE II (AZ004100115)			\$130,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost	
ID0332	LG- Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Site Work (1480)-Fence Painting,Non-Dwelling Exterior (1480)-Paint and Caulking)	Non-routine painting of the exterior of Lander Gardens Complex which includes both dwelling and non-dwelling buildings that are severely deteriorated.		\$100,000.00	
ID0419	Lander Gardens - Unit Modernization(Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Perform the necessary non-routine modifications to vacated units as they become available. Due to a low vacancy rate as a unit becomes available it will be put on off line status undergo Modernization.		\$30,000.00	
	Subtotal of Estimated Cost			\$2,546,086.00	

Work Statement for Year 4

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	AUTHORITY-WIDE (NAWASD)			\$927,086.00
ID0106	2025 - Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administrative costs necessary for the planning, design, implementation and monitoring of physical and Management Improvements.		\$254,608.00
ID0107	2025 - Operations(Operations (1406))	24% of the total grant amount to be distributed to the AMPS.		\$611,060.00
ID0108	2025 - Management Improvements (Management Improvement (1408)-Empowerment Activities,Management Improvement (1408)-Equal Opportunity,Management Improvement (1408)- Other)	PHA Homeowner Activities. Training for PHA staff in operations, procurement and procedures.		\$61,418.00
	MIXED FINANCE DEVELOPMENT TUCSON HOUSE (AZ004000048)			\$57,000.00
ID0291	Contract Administration - Relocation Costs(Contract Administration (1480)-Relocation)	Anticipated resident relocation costs pending the award of the Choice Neighborhood Grant.		\$5,000.00
ID0292	Physical Plant Repairs(Non-Dwelling Construction - Mechanical (1480)-Central Boiler,Non-Dwelling Construction - Mechanical (1480)-Central Chiller,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Generator,Non-Dwelling Construction - Mechanical (1480)-Generator,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters,Non-Dwelling Construction -	Make the necessary repairs "as needed" to HVAC, boilers, chillers, pumps, piping, generator, motors that provide heating, cooling and domestic hot water to the building residents. Replace boiler & chiller controls, replace boiler & chiller tubes. Replace condenser circulating pump.		\$20,000.00

Work Statement for Year 4

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0294	Bathroom Modifications(Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Plumbing)	Tub, showers, surrounds, sinks and vanities are in need of specific non-routine repairs in units: 1025, 1108, 1214, 1323, 1408, 1509, 1615, and 1608.		\$12,000.00
ID0295	Site Improvements(Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving)	Make necessary repairs "as needed" to parking lot asphalt pending the award of the Choice Neighborhood Grant.		\$10,000.00
ID0422	Building Repairs(Non-Dwelling Interior (1480)-Common Area Flooring)	Replace existing hallway flooring on (16th) floor.		\$10,000.00
	SCATTERED SITES (AZ004400111)			\$260,000.00
ID0312	AMP-4 Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Appliances,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Funce Painting,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-	Perform the necessary non-routine modifications to the following identified units: 1- 356 W Lerdo Rd (44) 2- 758 W Holladay Dr (131) 3- 918 W Virginia St (49) 4- 244 W Kentucky St (97) 5- 1339 E Ohio St (99)		\$100,000.00

Work Statement for Year 4

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0360	AMP-4 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace the existing deteriorated roof systems at following locations: 1- 6224 S. Sunrise Valley Dr. \$23K (158) 2- 6290 S. Sunrise Valley Dr. \$23K (159) 3- 1775 W Rue du Fleuve \$23K (177) 4- 332 W Corona Rd \$20K (1) 5- 1420 S TYNDALL AVE \$25K (35)		\$120,000.00
ID0364	AMP-4 Site Improvements (Dwelling Unit-Site Work (1480)-Other, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Pedestrian paving, Dwelling Unit-Site Work (1480)-Seal Coat, Dwelling Unit-Site Work (1480)-Striping, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Electric Distribution)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1- Parking- 1420 & 1422 S TYNDALL AVE \$20K 2- Lighting - N. 4th. Ave, Southland, Delano per A&E design from 2021 \$20K		\$40,000.00
	SCATTERED SITES (AZ004500112)			\$512,000.00
ID0313	AMP-5 Unit Modernization (Dwelling Unit-Exterior (1480)-Mail Facilities, Dwelling Unit-Exterior (1480)-Roofs, Dwelling Unit-Exterior (1480)-Windows, Dwelling Unit-Interior (1480)-Appliances, Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Interior Doors, Dwelling Unit-Interior (1480)-Interior painting (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Welchanical, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers, Dwelling Unit-Site Work (1480)-Asphalt -Concrete - Paving, Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Fence Painting, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Balconies-Porches-Railings-etc, Dwelling Unit-Exterior (1480)-Building Slab, Dwelling Unit-Exterior (1480)-Carports -Surface Garage, Dwelling Unit-Exterior (1480)-Exterior Doors, Dwelling Unit-Exterior (1480)-Carports - Lighting, Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Gutters - Downspouts, Dwelling Unit-Exterior (1480)-Landings and Railings)	Perform the necessary non-routine modifications to the identified units: 1- 2440 N Edith Blvd (77-87) 2- 2442 N Edith Blvd 3- 2444 N Edith Blvd 4- 2446 N Edith Blvd 5- 2462 N Edith Blvd 6- 380 E Pastime Rd. (A-T) (114-123)		\$120,000.00

Work Statement for Year 4

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0353	AMP-5 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated shingle or BUR roof systems with new at the following locations: 1- 3605 E Bellevue St Apt #1-4 (178-81) 2- 3917 E Hardy Dr. (31) 3- 2345 E 17th St Bldgs 1-4 (162-65)		\$150,000.00
ID0357	AMP-5 Site Improvements(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1-2835 N. Edith Blvd. 2-3556 E Blacklidge Dr.		\$100,000.00
ID0395	AMP-5 Replace Exterior Doors(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Paint and Caulking)	Replace deteriorated exterior metal doors and frames. Pastime Complex (40) units Seneca Complex (10) units 2400 Edith (24) 3425-27 E Presidio (4)		\$142,000.00
	SCATTERED SITES (AZ004600113)			\$152,000.00
ID0314	AMP-6 Unit Modernization (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gulling Unit-Exterior (1480)-Exterior (1480)-	Perform the necessary non-routine modifications to the following identified units: 1- 1511 N Sonoita Ave. (1) 2- 3471 S Fairbanks Ave (53) 3- 7417 E Vancouver Dr (76) 4- 5611 E Scarlett St (10)		\$120,000.00

Work Statement for Year 4

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0349	AMP-6 Water Heaters (Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Interior (1480)-Plumbing, Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters)	Deteriorated water heaters have reached the end of their life expectancy and need to be replaced with new high efficiency models. 1- 5411 E. Lee St (1-8) 2- 1715-29 N. Beverly Blvd. (1-8)		\$32,000.00
	POSADAS SENTINEL, PH. I (AZ004000051)			\$313,000.00
ID0345	Posadas 140 - Water Heaters(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters)	Deteriorated water heaters have reached the end of their life expectancy and need to be replaced with new high efficiency models. Units 31-40 of 60		\$25,000.00
ID0404	Posadas 140 - Roof Replacement(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings- etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Non- Dwelling Exterior (1480)-Roofs)	Replace identified existing deteriorated roof systems at the following locations: PHA- (30-31) - 470 W Armijo St. #1&2 Scattered - Unit 16 - 1916 W Calle Guadalajara Unit 18 - 6224 S Logger Dr Unit 19 - 6260 S Mero Court Unit 20 - 6151 S Avenue de la Chandelle		\$122,000.00
ID0408	Posadas 140- Replace HVAC System (Dwelling Unit-Exterior (1480)-Other, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Plumbing, Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems, Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System)	Replace deteriorated HVAC systems at the following locations: PHA- (30-31) - 470 W Armijo St. #1& 2		\$16,000.00
ID0412	Posadas 140- Site Work(Dwelling Unit-Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)- Landscape)	Phase II - Landscaping per A&E design.		\$50,000.00

Work Statement for Year 4

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0435	Posadas - Unit Modernization(Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Interior (1480)-Buthoom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Cluber,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Encing,Dwelling Uni	Perform the necessary non-routine modifications to the following identified units: Unit 16 - 1916 W Calle Guadalajara Unit 18 - 6224 S Logger Dr Unit 19 - 6260 S Mero Court Unit 20 - 6151 S Avenue de la Chandelle		\$100,000.00
	SCATTERED SITES (AZ004300110)			\$255,000.00
ID0371	AMP-3 Site Improvements -Parking(Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1843-1853 N. 4th. Ave.		\$15,000.00
ID0396	AMP-3 Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Baltroom Counters and Sinks,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Theroid (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site	Perform the necessary non-routine modifications to the following identified units: 1- 1740 W King St (123) 2- 1122 W Knox PL (86) 3- 1615 W Niagara St (91) 4- 1302 W Knox Pl (87) 5- 871 W Calle Ventura (84)		\$120,000.00

Part II: Sup	oporting Pages - Physical Needs Work Statements (s)			
Work State	ment for Year 4 2025			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Lighting, Dwelling Unit-Site Work (1480)-Seal Coat, Dwelling Unit-Site Work (1480)-Sewer Lines - Mains, Dwelling Unit-Site Work (1480)-Water Lines/Mains, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Interior Doors, Dwelling Unit-Interior (1480)-Interior Painting (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets)			
ID0398	AMP-3 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace the existing deteriorated roof systems at following locations: 1- 1717 S Via Hondo \$16K (55) 2- 802-04 W Glenn St \$48K (101-02) 3- 842-44 W Glenn St \$48K (102-03)		\$120,000.00
	LANDER APTS - PHASE II (AZ004100115)			\$70,000.00
ID0385	LG- Site Improvement - Plumbing A&E(Contract Administration (1480)-Other Fees and Costs)	Procure an A&E firm to design plans for the replacement of deteriorated main water supply system to all Lander Gardens complex and provide a professional cost estimate.		\$15,000.00
ID0392	LG- Kitchen & Bath Rehab(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Plumbing)	Kitchen & Bath cabinets, counter tops, faucets, sinks, are deteriorated and in need of replacement. Bldgs. (1,2,3 of 13)		\$25,000.00
ID0416	Lander Gardens - Unit Modernization(Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom	Perform the necessary non-routine modifications to vacated units as they become available. Due to a low vacancy rate as a unit becomes available it will be put on off line status undergo Modernization.		\$30,000.00

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)					
Work State	ment for Year 4 2025	j				
Identifier	Development Number/Name		General Description of Major Work Categories	Quantity	Estimated Cost	
	Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical))			•		
	Subtotal of Estimated Cost				\$2,546,086.00	

Work Statement for Year 5

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	SCATTERED SITES (AZ004600113)			\$230,000.00
ID0247	AMP-6 Site Improvements (Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Packing,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1715-1729 N Beverly Ave.		\$30,000.00
ID0442	AMP-6 Unit Modernization (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Openation (2480)-Exterior (1480)-Exterior (1480)-Boother,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Exterior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Perform the necessary non-routine modifications to the following identified units: 1-8571 E Ruby Dr. (70) 2-3501 S. Prudence Rd. (72) 3-7994 E. Tulip Tree Dr. (124) 4-2922 S. Portia Ave. (110)		\$100,000.00
ID0446	AMP-6 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Other)	Replace identified existing deteriorated shingle or BUR roof systems with new. 5644 E Hawthorne Street (2) 5901 E 23rd St (3) 5764 E Eastland St (4) 6345 E Eli Drive (5)		\$100,000.00
	MIXED FINANCE DEVELOPMENT TUCSON HOUSE (AZ004000048)			\$57,000.00

Work Statement for Year 5

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0280	Contract Administration - Relocation Costs(Contract Administration (1480)-Relocation)	Anticipated resident relocation costs pending the award of the Choice Neighborhood Grant.		\$5,000.00
ID0381	Site Improvements(Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)- Striping)	Make necessary repairs "as needed" to parking lot asphalt pending the award of the Choice Neighborhood Grant.		\$10,000.00
ID0414	Bathroom Modifications(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Tub, showers, surrounds, sinks and vanities are in need of specific non-routine repairs in units: 606, 507, 1504, 721, 924, 524, 204, 1218		\$12,000.00
ID0423	Building Repairs(Non-Dwelling Interior (1480)-Common Area Flooring)	Replace existing hallway flooring on (16th) floor.		\$10,000.00
ID0451	Physical Plant Repairs(Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Central Boiler,Non-Dwelling Construction - Mechanical (1480)-Central Chiller,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Electric Distribution,Non-Dwelling Construction - Mechanical (1480)-Generator,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters,Non-Dwelling Construction - Mechanical (1480)-Water Distribution)	Make the necessary repairs "as needed" to HVAC, boilers, chillers, pumps, piping, generator, motors that provide heating, cooling and domestic hot water to the building residents. Replace boiler & chiller controls, replace boiler & chiller tubes. Replace condenser circulating pump.		\$20,000.00
	LANDER APTS - PHASE II (AZ004100115)			\$235,000.00
ID0415	Lander Gardens - Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom	Perform the necessary non-routine modifications to vacated units as they become available. Due to a low vacancy rate as a unit becomes available it will be put on off line status undergo Modernization.		\$30,000.00

Work State	ment for Year 5 2026			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Interior Doors, Dwelling Unit-Interior (1480)-Interior Painting (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers)			
ID0420	LG- Kitchen & Bath Rehab(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing)	Kitchen & Bath cabinets, counter tops, faucets, sinks, are deteriorated and in need of replacement. Bldgs. (4A, B, C and 5 of 13)		\$30,000.00
ID0421	LG- Site Improvement - Plumbing(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace deteriorated plumbing system with new per A&E plan design from 2025.		\$175,000.00
	SCATTERED SITES (AZ004300110)			\$220,000.00
ID0426	AMP-3 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace the existing deteriorated roof systems at following locations: 2014 W Romany Rd (56) 415 E Wilcox Dr (58) 417 E Wilcox Dr (59) 1367 W El Rio Dr (63) 1445 W El Rio Dr (66) 1455 W El Rio Dr (66) 14702 W Pueblo Vista Blvd (68) 1958 S Mistletoe Cir (70) 2155 S San Jose Dr (71)		\$120,000.00
ID0427	AMP-3 Unit Modernization(Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,	Perform the necessary non-routine modifications to the following identified units: 2014 W Romany Rd (56) 414 E Alturas St (57) 415 E Wilcox Dr (58) 417 E Wilcox Dr (59)		\$100,000.00

Work Statement for Year 5 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Dwelling Unit-Interior (1480)-Appliances, Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Interior Doors, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Whechanical, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Site Work (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Seal Coat, Dwelling Unit-Site Work (1480)-Sewer Lines - Mains, Dwelling Unit-Site Work (1480)-SCATTERED SITES (AZ004400111)			\$220,000.00
ID0428	AMP-4 Unit Modernization (Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Encring,Dwelling Unit-Site Work (1480)-Encring,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Light	Perform the necessary non-routine modifications to the following identified units: 3450 S Belmar Ave (78) 403 W Kentucky St (92) 337 E Columbia St (93) 3058 E Kaibab Vista (95) 5106 S Fremont Dr (102)		\$100,000.00
ID0429	Seal Coat Dwelling Unit-Site Work (1480)-Sewer Lines - Mains Dwelling Unit-Site Work (1480)- AMP-4 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace the existing deteriorated roof systems at following locations: 1802 S Norris Ave (2-9) \$120K 827 W Montana St (94) \$20K 3058 E Kaibab Vista (95) \$20K 1339 E Ohio St (99) \$20K		\$120,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s) Work Statement for Year 5 2026				
	!	635 W Calle Medina (103) \$20K 6929 S Missiondale Rd (104) \$20K 1711 E Oregon St (105) \$20K		
	POSADAS SENTINEL, PH. I (AZ004000051)			\$369,000.00
ID0437	Posadas 140 - Water Heaters(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters)	Deteriorated water heaters have reached the end of their life expectancy and need to be replaced with new high efficiency models. Units 41 - 50 of 60		\$25,000.00
ID0438	Posadas 140- Site Work(Dwelling Unit-Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)- Landscape)	Phase II - Landscaping per A&E design.		\$50,000.00
ID0439	Posadas 140 - Roof Replacement(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Roofs)	Replace identified existing deteriorated roof systems at the following locations: PHA - (37-38) - 475 W 19th. St. #1&2 PHA - (42-43) - 484 W La Paz St. #1&2 PHA - (47-48) - 492 W 21st. St. #1&2 Scattered Sites Unit 21 - 6264 S Argosy Unit 25 - 2527 N Fair Oaks Ave Unit - 26 2894 E Via Genovesa Unit 28 - 2978 E Via Genovesa		\$156,000.00
ID0440	Posadas 140- Replace HVAC System (Dwelling Unit-Exterior (1480)-Other, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Plumbing, Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems, Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System)	Replace deteriorated HVAC systems at the following locations: PHA - (37-38) - 475 W 19th. St. #1.#2 PHA - (42-43) - 484 W La Paz St. #1.#2 PHA - (47-48) - 492 W 21st. St. #1.#2		\$48,000.00

Work Statement for Year 5

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0441	Posadas - Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Welling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Pumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fence,Dwelling Unit-Site Work (1480)-Fence,Dwelli	Perform the necessary non-routine modifications to the following identified units: Unit 21 - 6264 S Argosy Unit 25 - 2527 N Fair Oaks Ave Unit - 26 2894 E Via Genovesa Unit 28 - 2978 E Via Genovesa		\$90,000.00
	SCATTERED SITES (AZ004500112)			\$310,000.00
ID0443	AMP-5 Unit Modernization(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Counters and Sinks,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Cher,Dwelling Unit-Site Work (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Bundstape,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work	Perform the necessary non-routine modifications to the identified units: 1- 380 E Pastime Rd. (A-T) 2- 4825 E Winsett St (2) 3- 4842 E Melissa St (3) 4- 1421 E Manlove St (4) 5- 2920 E 19th St (5)		\$100,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
Lines - Mains,Dwelling Unit-Site Work (1480)-Water Lines/Mains)				
ID0444	AMP-5 Roof Replacement(Dwelling Unit-Exterior (1480)-Roofs)	Replace identified existing deteriorated shingle or BUR roof systems with new at the following locations: 1- 4825 E Winsett St (2) 2- 4842 E Melissa St (3) 3- 1421 E Manlove St (4) 4- 2920 E 19th St (5)		\$110,000.00
ID0445	AMP-5 Site Improvements(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping) Striping)	Make the necessary repairs to deteriorated parking lots to include: asphalt, striping, signage, concrete apron etc. at the following locations: 1-3325-27 E Glenn St \$40K + \$20K Lighting 2-1715-1729 N Beverly Ave - Parking Lot \$40K		\$100,000.00
	AUTHORITY-WIDE (NAWASD)			\$905,086.00
ID0448	2026 - Operations(Operations (1406))	24% of the total grant amount to be distributed to the AMPS.		\$611,060.00
ID0449	2026 - Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administrative costs necessary for the planning, design, implementation and monitoring of physical and Management Improvements.		\$254,608.00
ID0450	2026 - Management Improvements (Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other)	PHA Homeowner Activities. Training for PHA staff in operations, procurement and procedures.		\$39,418.00

Part II: Supporting Pages - Physical Needs Work Statements (s)					
Work Stater	Work Statement for Year 5 2026				
Identifier	Development Number/Name		General Description of Major Work Categories	Quantity	Estimated Cost
	Subtotal of Estimated Cost				\$2,546,086.00

Part III: Supporting Pages - Management Needs Work Statements (s)			
Work Statement for Year 1 2022			
Development Number/Name General Description of Major Work Categories	Estimated Cost		
Housing Authority Wide			
2022 - Management Improvements(Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other)	\$52,418.00		
2022 - Operations(Operations (1406))	\$611,060.00		
2022 - Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	\$254,608.00		
Subtotal of Estimated Cost	\$918,086.00		

Part III: Supporting Pages - Management Needs Work Statements (s)			
Work Statement for Year 2 2023			
Development Number/Name General Description of Major Work Categories	Estimated Cost		
Housing Authority Wide			
2023 - Management Improvements(Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other)	\$50,418.00		
2023 - Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	\$254,608.00		
2023 - Operations(Operations (1406))	\$611,060.00		
Subtotal of Estimated Cost	\$916,086.00		

Part III: Supporting Pages - Management Needs Work Statements (s)			
Work Statement for Year 3 2024			
Development Number/Name General Description of Major Work Categories	Estimated Cost		
Housing Authority Wide			
2024 - Operations(Operations (1406))	\$611,060.00		
2024 - Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	\$254,608.00		
2024 - Management Improvements(Management Improvement (1408)-Other, Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity)	\$53,418.00		
Subtotal of Estimated Cost	\$919,086.00		

Part III: Supporting Pages - Management Needs Work Statements (s)			
Work Statement for Year 4 2025			
Development Number/Name General Description of Major Work Categories	Estimated Cost		
Housing Authority Wide			
2025 - Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	\$254,608.00		
2025 - Operations(Operations (1406))	\$611,060.00		
2025 - Management Improvements (Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other)	\$61,418.00		
Subtotal of Estimated Cost	\$927,086.00		

Part III: Supporting Pages - Management Needs Work Statements (s)		
Work Statement for Year 5 2026		
Development Number/Name General Description of Major Work Categories	Estimated Cost	
Housing Authority Wide		
2026 - Operations(Operations (1406))	\$611,060.00	
2026 - Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	\$254,608.00	
2026 - Management Improvements (Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other)	\$39,418.00	
Subtotal of Estimated Cost	\$905,086.00	